

PATTERSON PUMP COMPANY / A Subsidiary of The Gorman –Rupp Co. P.O. Box 790 / Toccoa, Georgia 30577 / (706) 886-2101 / FAX (706) 886-0023 www.pattersonpumps.com

## General Pump Inspection and Maintenance Schedule Vertical In-Line Pumps

## Excludes motors, engines, gear drives, VFD's, and controls.

Actions required only for specific pump types are so noted. The symbol (**■**) used in the table below indicates that the action indicated may not be applicable to a specific pump of a particular type. For more information regarding inspection and maintenance requirements refer to the Patterson O & M manual supplied with the pump. Contact Patterson Pump Company if assistance is needed to determine the inspection and service requirements for a specific pump.

Inspect ( • ) or service (•) at the indicated calendar time or	4 hours	Routinely	Monthly	2000 hours or 3 months	4000 hours or 6 months	8000 hours or 12 months
run time interval – whichever comes first Unusual noise	4 nours	Koutiliery	Montiny	5 montuis	o montiis	12 months
Unusual vibration		· ·				
Unusual temperature		· ·				
Leaks in pump or piping		· · ·				
Pressure gauge readings		· · ·				
Visual inspection of equipment general condition		· ·				
Anytime a pump is opened, inspect the running clearances and restore them to original specifications if the running clearances have doubled (adjust ring clearances if so supplied or install new wear rings)		ו				
Anytime a pump is opened, inspect the impeller for corrosion or excessive wear.		<b>↓</b> •				
Packing box – verify slight leakage (if excessive, adjust gland or seal water valve; replace packing if required) ■		¥ •				
Mechanical seal (should be no leakage)		~				
Drain lines are working properly		~				
Operate the pump			>			
Replace packing (all packing; not just the outermost ring)					•	
Clean and oil gland bolts (packed pumps)					•	
Verify free movement of packing glands (packed pumps)					~	
Clean packing box						•
Perform a comparative field test (flow, pressures, and power) with calibrated instruments. Restore internal running clearances if results are unsatisfactory (install new wear rings).						¥ •
Remove packing and inspect sleeve(s). Replace if worn. (packed pumps) ■						¥•

Issue 020907